

CADILLAC P1762: TRANSMISSION MODE SWITCH SIGNAL MESSAGE

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$345
Can I Still Drive?	:	Yes

What Does The Cadillac P1762 Code Mean?

The engine speed is 400 RPM or greater for 5 seconds. No other CAN errors are present.

What Are The Potential Causes Of The Cadillac P1762 Code?

The TCM detects an error in the rolling count value that does not match with the BCM.

Reference Sources

[Cadillac P1762](#), DTCDECODE.