

CADILLAC P1792: ECM TO TCM ENGINE COOLANT SIGNAL (4L30-E)

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$200
Can I Still Drive?	:	Yes

What Does The Cadillac P1792 Code Mean?

Key on or engine running; and the PCM detected the ECT sensor signal was below the lower or over the upper limit, or that the ECT signal was unreliable for one second. The engine temperature signal is sent to the TCM by the PCM via a controller area network

What Are The Potential Causes Of The Cadillac P1792 Code?

- Perform the Onboard Diagnostic System Check
- Read and record any the codes. For multiple code situations – repair this code (P1792) before repairing any other codes.

Reference Sources

GM, 2013, [Service Bulletin](#) - Prior To Any Circuit Testing.