

CADILLAC P1795: THROTTLE PLATE POSITION INVALID DATA RECEIVED

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$650-\$900
Can I Still Drive?	:	No

What Does The Cadillac P1795 Code Mean?

Engine started, system voltage at 8-18v, no other CAN codes set, and the TCM received invalid throttle plate position data from the PCM for 2 seconds. The PCM sends throttle plate position data to the TCM. The data is sent to the TCM via the CAN.

How Can You Fix The Cadillac P1795 Code?

- Perform the Diagnostic System Check for the Engine Controls
- TCM may need to be replaced to repair this trouble code

Reference Sources

GM, 2013, [Service Bulletin](#) - Prior To Any Circuit Testing.