

What Does The Cadillac P1818 Code Mean?

Engine runtime over 5 seconds, system voltage from 8-18v, APP angle over 5%, vehicle speed over 5 mph.

What Are The Potential Causes Of The Cadillac P1818 Code?

- Manual shaft shift switch connector is open or shorted
- Manual shaft shift switch circuit is open or signals are shorted
- Manual shaft shift switch is damaged or out of adjustment
- TCM has failed

Reference Sources

GM, 2013, Service Bullettin - Prior To Any Circuit Testing.

