

CADILLAC P181D: INTERNAL MODE SWITCH 2 R1 CIRCUIT HIGH VOLTAGE

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$170-\$300
Can I Still Drive?	:	Yes

What Are The Potential Causes Of The Cadillac P181D Code?

The internal mode switch state does not match the selected gear for 3 seconds.

Reference Sources

[Cadillac P181D](#), DTCDECODE.