

CADILLAC P184B: INTERNAL MODE SWITCH 2 S CIRCUIT HIGH VOLTAGE

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$170-\$300
Can I Still Drive?	:	Yes

What Does The Cadillac P184B Code Mean?

The internal mode switch state does not match the selected gear for 3 seconds.

Reference Sources

[Cadillac P184B](#), DTCDECODE.