

What Does The Cadillac P1870 Code Mean?

Conditions for Setting the DTC. The following conditions are met for three TCC cycles with reported excessive TCC slip conditions: No TP DTCs <u>P0122</u> or <u>P0123</u> No VSS DTC <u>P0502</u> No TFT sensor DTCs <u>P0712</u> or <u>P0713</u> No 1-2 SS Valve DTCs <u>P0751</u>.

What Are The Potential Causes Of The Cadillac P1870 Code?

- A TFP Valve Position Switch malfunction could set DTC P1870.
- The following mechanical conditions could set DTC P1870:
 - A mechanical failure of the shift solenoid valves
 - A mechanical failure of the TCC Solenoid Valve

Reference Sources

Cadillac P1870, DTCDECODE.

