

CADILLAC P1873: TORQUE CONVERTER STATOR TEMP SWITCH CKT LOW

OVERVIEW

Severity	:	<div>High</div>
DIY Difficulty Level	:	<div>Intermediate</div>
Repair Cost	:	\$100-\$250
Can I Still Drive?	:	Yes

What Does The Cadillac P1873 Code Mean?

Conditions for Setting the DTC. No TFT DTCs P0712 or P0713. The TFT is less than 60°C (140°F). Torque converter stator temperature switch circuit indicates a hot mode. All conditions met for 5 seconds.

How Can You Fix The Cadillac P1873 Code?

- If the switch and external wiring checks okay, verify the circuit ground integrity through the transmission fluid cooler pipes.
- Inspect the wiring for poor electrical connections at the PCM. Look for the following conditions:
 - A bent terminal

Reference Sources

[Cadillac P1873](#), DTCDECODE.