

CADILLAC P1874: TORQUE CONVERTER STATOR TEMP SWITCH CKT HIGH

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$250
Can I Still Drive?	:	Yes (Short-term only)

What Does The Cadillac P1874 Code Mean?

Conditions for setting the DTC:

- No TFT DTCs [P0712](#) or [P0713](#)
- The TFT is greater than 140°C (284°F).
- Torque converter stator temperature switch circuit does not indicate a hot mode.
- All conditions met for 15 seconds.

How Can You Fix The Cadillac P1874 Code?

- If the switch and external wiring checks okay, verify the circuit ground integrity through the transmission fluid cooler pipes.
- Inspect the wiring for poor electrical connections at the PCM

Reference Sources

[Cadillac P1874](#), DTCDECODE.