

CADILLAC U1097: NO COMMUNICATION WITH DRIVER INFORMATION CENTER

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Cadillac U1097 Code Mean?

Key on, and a message from a learned ID number was not detected for the five seconds. Modules on the Class 2 circuit monitor for data communications during vehicle operation. When a module receives a message for critical data, the module records the identify.

What Are The Potential Causes Of The Cadillac U1097 Code?

- DIC Class 2 circuit is open, shorted to ground or to B+
- DIC ignition power circuit has a high resistance condition
- DIC main ground circuit(s) has a high resistance condition
- DIC (module) may have failed and is pulling the circuit low

Reference Sources

[Cadillac U1097](#), DTCDECODE.