CADILLAC U1300: CLASS 2 SHORT TO GROUND		
		OVERVIEW
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

## What Does The Cadillac U1300 Code Mean?

Conditions for Setting the DTC. The module detects that the cass 2 serial data line is shorted to ground for at least 2.6 seconds.

## What Are The Potential Causes Of The Cadillac U1300 Code?

This DTC is not received as current because the cass 2 serial data line does not function during this condition.

## **Reference Sources**

GM, 2016 <u>Service Bullettin</u> - No Crank Key Stuck In Ignition Lock Cylinder Multiple ECM Codes And U1000 Set In Class 2 Modules.

