

CADILLAC U1300: CLASS 2 SHORT TO GROUND

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Cadillac U1300 Code Mean?

Conditions for Setting the DTC. The module detects that the class 2 serial data line is shorted to ground for at least 2.6 seconds.

What Are The Potential Causes Of The Cadillac U1300 Code?

This DTC is not received as current because the class 2 serial data line does not function during this condition.

Reference Sources

GM, 2016 [Service Bulletin](#) - No Crank Key Stuck In Ignition Lock Cylinder Multiple ECM Codes And U1000 Set In Class 2 Modules.