UI. CI	LASS 2 SHORT TO BATTER'
	OVERVIEW
•	Medium
:	Intermediate
:	\$75-\$200
:	Yes
	:

What Does The Cadillac U1301 Code Mean?

Conditions for Setting the DTC. The module detects that the class 2 serial data line is shorted to battery voltage for at least 2.6 seconds.

This DTC is not received as current because the class 2 serial data line does not function during this condition.

Reference Sources

Cadillac U1301, DTCDECODE.

