

## CADILLAC U1511: INTER-DEVICE DEDICATED BUS LOST COMMUNICATION WITH DEVICE 1

### OVERVIEW

|                      |   |                                    |
|----------------------|---|------------------------------------|
| Severity             | : | <div><div>Medium</div></div>       |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost          | : | \$75-\$200                         |
| Can I Still Drive?   | : | Yes                                |

### What Does The Cadillac U1511 Code Mean?

- Both DTC U1511 and U1512 will set if an open/high resistance in the local interconnect network bus circuit is between the door module and the first splice.
- Only 1 DTC (U1511 or U1512) will set if an open/high resistance in the local interconnect net

### Reference Sources

- GM, 2013, [Service Bulletin](#) - False Low Beam Failure Message Displayed.
- GM, 2015, [Service Bulletin](#) - Service Adaptive Headlamp Message Displayed, DTCs B257C and B257D.
- GM, 2017, [Service Bulletin](#) - Active Shutters Inoperative, Malfunction Indicator Lamp (MIL) Illuminated - DTCs P059F, U1501, U1510, U1511 Set.
- GM, 2017, [Service Bulletin](#) - Stop/Start System (RPO KL9) Inhibited with Malfunction Indicator Light (MIL) ON - DTC P16DC, P15FF, U01B0, U0284, U0285, U1345, U135A, U135E, U1501, U1510, U1511 Set.
- GM, 2019, [Service Bulletin](#) - Stop/Start System Inhibited with Malfunction Indicator Light (MIL) ON - DTC P16DC, P15FF, P305D, P305E, U01B0, U0284, U0285, U1345, U135A, U135E, U1501, U1510, U1511 Set.
- GM, 2019, [Service Bulletin](#) - PIT5698 LIN Bus Diagnostic Information.
- GM, 2019, [Service Bulletin](#) - Active Shutters Inoperative, Malfunction Indicator Lamp (MIL) Illuminated - DTCs P059F, U1501, U1510, U1511 Set.

- GM, 2020 [Service Bulletin](#) - PIT5698A LIN Bus Diagnostic Information.