CADILLAC U1512: INTER-DEVICE DEDICATED BUS LOST COMMUNICATION WITH DEVICE 2

OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$75-\$200

Can I Still Drive? : Yes (Short-term only)

What Does The Cadillac U1512 Code Mean?

Condition for setting the DTC: The system voltage is between 9-16 volts.

What Are The Potential Causes Of The Cadillac U1512 Code?

- Both DTC <u>U1511</u> and U1512 will set if an open/high resistance in the local interconnect network bus circuit is between the door module and the first splice.
- Only 1 DTC (U1511 or U1512) will set if an open/high resistance in the local interconnect net.

Reference Sources

- GM, 2012, Service Bullettin False Low Beam Failure Message Displayed.
- GM, 2013, Service Bullettin False Low Beam Failure Message Displayed./li>
- GM, 2015, <u>Service Bullettin</u> Service Adaptive Headlamp Message Displayed, DTCs B257C and B257D.
- GM, 2019, Service Bullettin PIT5698 LIN Bus Diagnostic Information.
- GM, 2020 Service Bullettin PIT5698A LIN Bus Diagnostic Information.

