

## CADILLAC U1883: HYBRID CONTROL MODULE (HCM) LOST COMMUNICATION WITH DRIVER DOOR MODULE (DDM)

### OVERVIEW

|                      |   |                                    |
|----------------------|---|------------------------------------|
| Severity             | : | <div><div>Medium</div></div>       |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost          | : | \$75-\$200                         |
| Can I Still Drive?   | : | <b>Yes</b> (Short-term only)       |

### What Does The Cadillac U1883 Code Mean?

Voltage supplied to the module is in the normal operating voltage range of 9-16 volts.

### What Are The Potential Causes Of The Cadillac U1883 Code?

Ensure all power and ground circuits to the electric-hydraulic power steering (EHPS) module including the motor are tested. A loss of voltage or ground to the EHPS hydraulic motor as well as to the module may be the causes.

### Reference Sources

[Cadillac U1883](#), DTCDECODE.