

CADILLAC U1889: HYBRID CONTROL MODULE (HCM) LOST COMMUNICATION WITH BODY CONTROL MODULE (BCM)

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$45-\$800
Can I Still Drive?	:	No

What Does The Cadillac U1889 Code Mean?

Conditions for setting the DTC: Voltage supplied to the module is in the normal operating voltage range of 9-16 volts.

What Are The Potential Causes Of The Cadillac U1889 Code?

Ensure all power and ground circuits to the electric-hydraulic power steering (EHPS) module including the motor are tested. A loss of voltage or ground to the EHPS hydraulic motor as well as to the module may be the causes.

Reference Sources

[Cadillac U1889](#), DTCDECODE.