

CHEVROLET C1277: REQUESTED TORQUE SIGNAL CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$300-\$1000
Can I Still Drive?	:	Yes (Short-term only)

What Are The Potential Causes Of The Chevrolet C1277 Code?

- An open in the delivered torque circuit.
- An short to ground or voltage in the delivered torque circuit.
- A wiring problem, terminal corrosion, or poor connection in the delivered torque circuit.

Reference Sources

[Chevrolet C1277](#), DTCDECODE.