

CHEVROLET C12B6: HIGH PRESSURE ACCUMULATOR PRESSURE SENSOR SHORT TO GROUND OR OPEN

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chevrolet C12B6 Code Mean?

This code means that the HPA (High Pressure Accumulator) pressure sensor is either open or shorted to ground.

What Are The Potential Causes Of The Chevrolet C12B6 Code?

Below are some potential causes of this DTC:

- A short to battery is detected on the sensor signal circuit.
- A short to ground or open is detected on signal circuit.
- Signal is erratic and changes faster than physically allowed.

Reference Sources

[Chevrolet Volt Hybrid DTC](#) - OBDG01 HYBRID Diagnostics Document, page 563.