

CHEVROLET P1021: CNG FUEL INJECTOR 1 CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$350-\$850
Can I Still Drive?	:	No

What Does The Chevrolet P1021 Code Mean?

Engine started, system voltage from 6-18v, and the FICM detected an incorrect voltage condition on the circuit that controls the CNG Fuel Injector 1 operation during the CCM test.

What Are The Potential Causes Of The Chevrolet P1021 Code?

- CNG fuel injector 1 control circuit is open or shorted to ground
- CNG fuel injector 1 is damaged or it has failed
- FICM has failed

Reference Sources

[Chevrolet P1021](#), DTCDECODE.