

CHEVROLET P1023: CNG FUEL INJECTOR 3 CIRCUIT MALFUNCTION

OVERVIEW

Severity	:		High
DIY Difficulty Level	:		Intermediate
Repair Cost	:	\$350-\$850	
Can I Still Drive?	:	No	

What Does The Chevrolet P1023 Code Mean?

Engine started, system voltage from 6-18v, and the FICM detected an incorrect voltage condition on the circuit that controls the CNG Fuel Injector 3 operation during the CCM test.

What Are The Potential Causes Of The Chevrolet P1023 Code?

- CNG fuel injector 3 control circuit is open or shorted to ground
- CNG fuel injector 3 is damaged or it has failed
- FICM has failed

Reference Sources

[Chevrolet P1023, DTCDECODE.](#)