

## What Does The Chevrolet P1024 Code Mean?

Engine started, system voltage from 6-18v, and the FICM detected an incorrect voltage condition on the circuit that controls the CNG Fuel Injector 4 operation during the CCM test.

## What Are The Potential Causes Of The Chevrolet P1024 Code?

- CNG fuel injector 4 control circuit is open or shorted to ground
- CNG fuel injector 4 is damaged or it has failed
- FICM has failed

## **Reference Sources**

Chevrolet P1024, DTCDECODE.

