

CHEVROLET P1024: CNG FUEL INJECTOR 4 CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$350-\$850
Can I Still Drive?	:	No

What Does The Chevrolet P1024 Code Mean?

Engine started, system voltage from 6-18v, and the FICM detected an incorrect voltage condition on the circuit that controls the CNG Fuel Injector 4 operation during the CCM test.

What Are The Potential Causes Of The Chevrolet P1024 Code?

- CNG fuel injector 4 control circuit is open or shorted to ground
- CNG fuel injector 4 is damaged or it has failed
- FICM has failed

Reference Sources

[Chevrolet P1024](#), DTCDECODE.