

CHEVROLET P113A: EXHAUST GAS TEMPERATURE SENSORS 3-4 NOT PLAUSIBLE

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$50-\$1550
Can I Still Drive?	:	No

What Does The Chevrolet P113A Code Mean?

The ECM detects, at engine start, that a temperature difference of greater than 30°C (54°F), exists between exhaust gas temperature sensor 3 and exhaust gas temperature sensor 4.

Conditions for setting the DTC: The ignition has been OFF for greater than 8 hours. The engine is running. The ambient air temperature is greater than -60°C (-76°F). DTC P113A runs once per key cycle when the above conditions are met.

Reference Sources

[Chevrolet P113A](#), DTCDECODE.