

## CHEVROLET P1191: INTAKE AIR DUCT LEAK

### OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$350
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Chevrolet P1191 Code Mean?

Conditions for Setting the DTC. DTCs [P0405](#), [P0406](#), [P0102](#) and [P0103](#) are not set. All EGR tests have been completed (internal to PCM). Intake leak greater than calibrated value (internal to PCM).

### What Are The Potential Causes Of The Chevrolet P1191 Code?

The most likely cause of failure is a leaky intake duct after the MAF sensor. To run the diagnostic test the engine must be at operating temperature, vehicle in drive at idle for approximately 1 minute, then with vehicle in park hold engine rpm steady.

### Reference Sources

[Chevrolet P1191](#), DTCDECODE.