

CHEVROLET P1255: FUEL PUMP CONTROL MODULE DRIVER OVER-TEMPERATURE

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$100-\$350
Can I Still Drive?	:	No

What Does The Chevrolet P1255 Code Mean?

The FPCM detects that the fuel pressure 5-volt reference is above or below a predetermined voltage threshold.

Reference Sources

- GM, 2012, [Service Bulletin](#).
- GM, 2013, [Service Bulletin](#).
- GM, 2014, [Service Bulletin](#).