

CHEVROLET P1381: MISFIRE DETECTED - NO COMMUNICATION WITH BRAKE CONTROL MODULE

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$100-\$1000
Can I Still Drive?	:	No

What Does The Chevrolet P1381 Code Mean?

The vehicle speed is greater than 8 km/h (5 mph). The engine speed is less than 8,192 RPM. The engine load is less than 60 percent. Engine misfire is detected and DTC P0300 sets with the MIL illuminated. DTCs P1380 and P1381 run continuously when the above conditions are met.

- An EBCM malfunction exists for greater than 10 s, preventing the ECM from receiving rough road detection data.
- Engine misfire is detected and DTC P0300 sets with the MIL illuminated.

Reference Sources

- [2000 Chevrolet Camaro and Pontiac Firebird Service Manual](#) - Volume 1, page 1123.
- GM, 2013, [Service Bulletin](#) - Prior To Any Circuit Testing.