

CHEVROLET P1410: FUEL TANK PRESSURE SYSTEM RANGE/PERFORMANCE

OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$150-\$350
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chevrolet P1410 Code Mean?

Engine started, fuel level from 25-75%, and the PCM detected an unexpected voltage on the Fuel Tank Pressure Control signal circuit with the fuel level over a value stored in memory.

What Are The Potential Causes Of The Chevrolet P1410 Code?

- Fuel tank pressure control solenoid control circuit is open, shorted to ground or to B+
- Fuel tank pressure control solenoid power circuit is open
- Fuel tank pressure control solenoid is damaged or has failed
- PCM has failed

Reference Sources

GM, 2013, [Service Bulletin](#) - Prior To Any Circuit Testing.