

CHEVROLET P1460: COOLING FAN CONTROL SYSTEM MALFUNCTION

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chevrolet P1460 Code Mean?

Key on, and the PCM detected the fan control circuit failed the output voltage check with the fan "on", conditions met for 5 seconds.

What Are The Potential Causes Of The Chevrolet P1460 Code?

- Cooling fan relay control circuit is open
- Cooling fan relay control circuit is shorted to ground
- Cooling fan relay power circuit is open
- Cooling fan relay is damaged or has failed
- PCM has failed

Reference Sources

GM, 2013, [Service Bulletin](#) - Prior To Any Circuit Testing.