

CHEVROLET P1481: COOLING FAN SPEED SIGNAL LOST

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chevrolet P1481 Code Mean?

The engine is running. System voltage is greater than 8.5 volts.

How Can You Fix The Chevrolet P1481 Code?

An inline connector could cause an intermittent DTC. Ensure to test for poor connections and pin retention at all inline connectors. Refer to system schematics for connector and locations.

Reference Sources

[Chevrolet P1481](#), DTCDECODE.