

CHEVROLET P1573: TRACTION CONTROL SYSTEM, LOSS OF ABS/TCS SERIAL DATA

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$320-\$1000
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chevrolet P1573 Code Mean?

Key on or engine running and the PCM detected an unexpected voltage condition on the serial data line to the EBTCM for over 500 ms.

What Are The Potential Causes Of The Chevrolet P1573 Code?

- Serial data circuit is open between the EBTCM and the PCM
- EBTCM has failed

Reference Sources

GM, 2013, [Service Bulletin](#) - Prior To Any Circuit Testing.