

CHEVROLET P15B9: ELECTRIC A/C COMPRESSOR CONTROL MODULE IGNITION ON/START SWITCH CIRCUIT LOW VOLTAGE

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$150-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chevrolet P15B9 Code Mean?

Hybrid powertrain control module 2 is awake. Vehicle power mode is Vehicle ON or Vehicle in Service Mode. System voltage greater than 10.25 V.

What Are The Potential Causes Of The Chevrolet P15B9 Code?

- Hybrid powertrain control module 2 is awake
- Vehicle power mode is Vehicle ON or Vehicle in Service Mode
- Hybrid powertrain control module 2 ignition input is active
- A/C compressor ignition input is not active and not greater than 5 V

Reference Sources

[Chevrolet P15B9](#), DTCDECODE.