

CHEVROLET P15F9: HYBRID SYSTEM ENGINE SPEED CONTROL INTERVENTION REQUEST TYPE SIGNAL MESSAGE COUNTER INCORRECT

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$150
Can I Still Drive?	:	No

What Does The Chevrolet P15F9 Code Mean?

This DTC indicates that the ECM detects that 10 of 16 counts/samples contain an error value.

Conditions for setting the DTC: The engine run time is greater than 0.5 s. No other CAN errors are present. DTC P15F9 runs continuously when the above conditions are met.

Reference Sources

[Chevrolet Volt Hybrid DTC](#) - OBDG01 HYBRID Diagnostics Document, page 176.