CHEVROLET P15F9: HYBRID SYSTEM ENGINE SPEED CONTROL INTERVENTION REQUEST TYPE SIGNAL MESSAGE COUNTER INCORRECT

OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$50-\$150

Can I Still Drive? : No

What Does The Chevrolet P15F9 Code Mean?

This DTC indicates that the ECM detects that 10 of 16 counts/samples contain an error value.

Conditions for setting the DTC: The engine run time is greater than 0.5 s. No other CAN errors are present. DTC P15F9 runs continuously when the above conditions are met.

Reference Sources

Chevrolet Volt Hybrid DTC - OBDG01 HYBRID Diagnostics Document, page 176.

