

## CHEVROLET P160C: ENGINE CALIBRATION INFORMATION NOT PROGRAMMED - GPCM

### OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$350-\$850
Can I Still Drive?	:	No

### What Does The Chevrolet P160C Code Mean?

The fuel injector calibration flow rate data is incorrect, or not programmed.

### Reference Sources

[Chevrolet P160C](#), DTCDECODE.