COMMAND			
		OVERVIEW	
Severity	:		High
DIY Difficulty Level	:		Advanced
Repair Cost	:	\$800-\$1500	
Can I Still Drive?	:	No	

What Does The Chevrolet P16F6 Code Mean?

The control module has detected the commanded transmission range state is not correct based upon internal calculations or by a comparison to input or output torque conditions.

Reference Sources

Chevrolet Volt Hybrid DTC - OBDG01 HYBRID Diagnostics Document, page 378.

