

CHEVROLET P179B: RANGE STATE COMMAND CIRCUIT

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$500-\$900
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chevrolet P179B Code Mean?

This DTC indicates that the control solenoid valve assembly has detected a Range State Command rolling count error for 2 seconds.

Conditions for setting the DTC: The engine is running. Ignition voltage is 8-18 V.

Reference Sources

[Chevrolet Volt Hybrid DTC](#) - OBDG01 HYBRID Diagnostics Document, page 323.