

CHEVROLET P1874: TORQUE CONVERTER STATOR TEMP SWITCH CKT HIGH

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$250
Can I Still Drive?	:	Yes

What Does The Chevrolet P1874 Code Mean?

Conditions for Setting the DTC. The TFT is less than 140°C (284°F). The torque converter stator temperature switch circuit does not indicate hot mode. All conditions are met for 15 seconds.

What Are The Potential Causes Of The Chevrolet P1874 Code?

- If the switch and the external wiring are OK, verify the circuit ground integrity through the transmission fluid cooler pipes.
- Inspect the wiring for poor electrical connections at the PCM. Inspect the wiring for poor electrical connections.

Reference Sources

GM, 2013, [Service Bulletin](#) - Prior To Any Circuit Testing.