

CHEVROLET P1AC9: HCM SERVICE CALIBRATION FAULT

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$75-\$350
Can I Still Drive?	:	No

What Does The Chevrolet P1AC9 Code Mean?

This code indicates that the internal fault detection is handled inside the control module. No external circuits are involved.

Conditions for setting the DTC:

- The module has received voltage on the ignition 0 voltage circuit.
- The module has turned ON and no configuration DTC are present.
- This diagnostic shall be run every 100 ms.
- Reference voltage is stable and accurate.

What Are The Potential Causes Of The Chevrolet P1AC9 Code?

- Faulty Hybrid Control Module (HCM)
- Hybrid Control Module (HCM) harness is open or shorted
- Hybrid Control Module (HCM) circuit poor electrical connection

Reference Sources

[Chevrolet P1AC9](#), DTCDECODE.