

## CHRYSLER B103F: REAR MODE DOOR TRAVEL RANGE TOO LARGE

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Chrysler B103F Code Mean?

The rear mode and temperature blend doors are controlled by a two wire actuator. The door actuator motor will rotate either clockwise or counter clockwise by reversing the polarity of the circuits depending on the command from the controller. The A/C Heater Control monitors the circuits for proper operation and will set a Diagnostic Trouble Code (DTC) if a fault is detected.

### What Are The Potential Causes Of The Chrysler B103F Code?

- Related DTCS Present
- Rear Mode Door Stops
- Rear Mode Door
- Rear Mode Door Actuator
- A/C Heater Control

### Reference Sources

[Chrysler B103F](#), DTCDECODE.