

CHRYSLER B1044: PANEL MODE DOOR 1 TRAVEL RANGE TOO SMALL

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chrysler B1044 Code Mean?

The A/C Heater Control uses a pulse feedback to the controller to detect the total door movement range. If the amount of pulses required to move the door completely in both directions is less than what the controller has stored in its memory, this DTC will set.

If an Actuator Calibration Test is performed and the A/C Heater Control detects a valid range of the door movement span in both directions, the DTC will change from Active to Stored and will stay in the controllers memory for 100 ignition cycles.

What Are The Potential Causes Of The Chrysler B1044 Code?

- Related DTCS Present
- Mode Door Binding
- Mode Door Actuator
- A/C Heater Control

Reference Sources

[Chrysler B1044](#), DTCDECODE.