

CHRYSLER B1084: LEFT HEATED SEAT SWITCH INPUT CIRCUIT PERFORMANCE

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chrysler B1084 Code Mean?

The HVAC Front A/C Heater Module contains various switches and knobs that are used to change the systems operation. Many of the switches are momentary switches which are normally open or in the Off position and the status changes when the switch button or knob is pushed or turned.

An active Diagnostic Trouble Code (DTC) indicates that the switch is stuck in an On position. A stored DTC indicates that the switch was stuck in a On position for more than four minutes but has since returned to its normal state of Off.

What Are The Potential Causes Of The Chrysler B1084 Code?

- Object Holding Switch In An On Position
- Front A/C Heater Module

Reference Sources

[Chrysler B1084](#), DTCDECODE.