

CHRYSLER B1096: FRONT RIGHT SEAT HEATER CONTROL CIRCUIT LOW

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	Yes

What Does The Chrysler B1096 Code Mean?

Ignition on, during the heated seat operation. This code is set immediately after the Heated Seat Module detects the control circuit shorted to ground

What Are The Potential Causes Of The Chrysler B1096 Code?

- (P188) Right Seat Heater B(+) Driver Shorted To Ground
- Seat Cushion Heater Element Shorted
- Seat Back Heater Element Shorted
- Heated Seat Module

Reference Sources

[Chrysler B1096](#), DTCDECODE.