

CHRYSLER B1098: FRONT RIGHT SEAT HEATER CONTROL CIRCUIT OPEN

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	Yes

What Does The Chrysler B1098 Code Mean?

Ignition on, during the heated seat operation. This code is set immediately after the Heated Seat Module detects an open in the seat heater B(+) driver circuit.

What Are The Potential Causes Of The Chrysler B1098 Code?

- (P188) Right Seat Heater B(+) Driver Wire Open
- (Z908) Ground Wire Open
- Seat Cushion Heater Element Open
- Seat Back Heater Element Open
- Heated Seat Module

Reference Sources

[Chrysler B1098](#), DTCDECODE.