

## CHRYSLER B10B5: CABIN HEATER 1 CONTROL CIRCUIT HIGH

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$500
Can I Still Drive?	:	Yes

### What Does The Chrysler B10B5 Code Mean?

If the Totally Integrated Power Module (TIPM) detects that the (K360) Cabin Heater 1 Relay Control circuit is shorted to voltage.

### What Are The Potential Causes Of The Chrysler B10B5 Code?

- (K360) Cabin Heater 1 Relay Control Circuit Shorted To Voltage
- Cabin Heater Relay
- Totally Integrated Power Module (TIPM)

### Reference Sources

[Chrysler B10B5](#), DTCDECODE.