

CHRYSLER B10B7: CABIN HEATER 2 CONTROL CIRCUIT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$500
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chrysler B10B7 Code Mean?

With the ignition on. An error message has been received over the CAN bus from the Totally Integrated Power Module (TIPM).

What Are The Potential Causes Of The Chrysler B10B7 Code?

- DTC Set In Totally Integrated Power Module (TIPM)
- Engine Control Module (ECM)

Reference Sources

[Chrysler B10B7](#), DTCDECODE.