

CHRYSLER B10BB: LEFT HEATED SEAT SWITCH INPUT CIRCUIT STUCK

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$100
Can I Still Drive?	:	Yes

What Does The Chrysler B10BB Code Mean?

Continuously. When the Heated Seat Switch in the Switch Bank is held in the on position for over 10 seconds, this code will set.

What Are The Potential Causes Of The Chrysler B10BB Code?

- (D506) Lin Bus Circuit Partial Short To Ground
- Switch Bank Stuck
- Instrument Cluster

Reference Sources

[Chrysler B10BB](#), DTCDECODE.