

## CHRYSLER B10BC: RIGHT HEATED SEAT SWITCH INPUT CIRCUIT STUCK

### OVERVIEW

|                      |   |                                    |
|----------------------|---|------------------------------------|
| Severity             | : | <div><div>Medium</div></div>       |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost          | : | \$50-\$100                         |
| Can I Still Drive?   | : | Yes                                |

### What Does The Chrysler B10BC Code Mean?

Continuously. When the Heated Seat Switch in the Switch Bank is held in the on position for over 10 seconds, this code will set.

### What Are The Potential Causes Of The Chrysler B10BC Code?

- (D506) Lin Bus Circuit Partial Short To Ground
- Switch Bank Stuck
- Instrument Cluster

### Reference Sources

[Chrysler B10BC](#), DTCDECODE.