

CHRYSLER B129A: DRIVER BLIND SPOT SENSOR-INCOMPATIBLE VERSION

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$150-\$500
Can I Still Drive?	:	Yes

What Does The Chrysler B129A Code Mean?

With the ignition on. Vehicle speed greater than 6 mph (9.6 km/h). This fault will present itself during a reflashing session. When the flashing tool attempts to enter the programming session, the Blind Spot Module (BSM) will query the sensors for their bootloader version.

If the returned version is not compatible with the BSM bootloader, the BSM will not allow the system to flash. This DTC will be set

What Are The Potential Causes Of The Chrysler B129A Code?

LEFT REAR BLIND SPOT SENSOR

Reference Sources

[Chrysler B129A](#), DTCDECODE.