CHRYSLER B142B: VES UNIT HIGH TEMPERATURE OVERVIEW Severity: Medium DIY Difficulty Level: Intermediate Repair Cost: \$50-\$345 Can I Still Drive?: Yes

What Does The Chrysler B142B Code Mean?

The DVD Player temperature is above 90°C (194°F).

What Are The Potential Causes Of The Chrysler B142B Code?

Dvd Player High Temperature

Reference Sources

Chrysler B142B, DTCDECODE.

